Johnson, James

From:

Monnig, Rob <rob.monnig@tetratech.com>

Sent:

Thursday, April 17, 2014 11:07 AM

To: Cc: Schaefer, Joe

Subject:

Johnson, James

Attachments:

FW: FW: Westlake HASP Westlake Landfill HASP.doc

Joe – Here's a draft HASP to go by. The hospital identified is:

Hospital Name: SSM DePaul Health Center

Address: 12303 DePaul Drive, Bridgeton, MO 63044

From: rclaytor@seagullenvirotech.com [mailto:rclaytor@seagullenvirotech.com]

Sent: Thursday, April 17, 2014 10:22 AM

To: Monnig, Rob

Subject: Re: FW: Westlake HASP

Yes, it is attached. I did not insert a site map. Names of people working at the site might need changing. I have not attached any SWP or ADH s.

On April 17, 2014 at 9:53 AM "Monnig, Rob" <<u>rob.monnig@tetratech.com</u>> wrote:

Hi Rick – How's the HASP? Is a rough draft available? Thanks!

From: Johnson, James [mailto:Johnson.James@epa.gov]

Sent: Thursday, April 17, 2014 9:47 AM

To: Monnig, Rob

Subject: Fw: Westlake HASP

From: Schaefer, Joe

Sent: Thursday, April 17, 2014 9:17:26 AM

To: Johnson, James

Cc: Kappelman, David; david.l.adams@lmco.com

Subject: Westlake HASP

James.

SERAS needs to write a HASP before mobilizing to Westlake next week. Does START have one already prepared we could borrow from?

Thanks,

Joe Schaefer Environmental Response Team US EPA (c)609-865-8111

07/4 40458643 /,0
Superfund

0400

Rick Claytor, CHMM
Sr. Environmental Scientist
Seagull Environmental Technologies, Inc.
Woman-Owned, 8(a) Firm
email: rclaytor@seagullenvirotech.com



Site Name: Westlake Landfill	Site Contact: David Kinroth			Telephone: 913-220-5887 (d				
Location: Bridgeton, Missouri	Client Contact: Eric Nold		Telephone: 816-718-4274-2534 (cell) 913-551-7488 (work)					
EPA ID No.	Prepa	red B	y: Rick Claytor			Date Pre	Date Prepared: 4/15/2014	
Project No. 9025.14.0058.000	Dates	of Ac	tivities: May 2014 f	orwar	d	Emergen	cy Response 🗌 Yes 🔀 No	
Objectives:		Site	Type: Check as ma	ny as	applicable.		•	
START will provide support to EPA Region 7 implementing an air monitoring plan to sample for landfill constituents prior to the isolation		\boxtimes	Active	\boxtimes	Landfill		Inner-City	
barrier installation around the Westlake landfill. The plan is to docum background conditions off the site prior to construction activities and construction.	ent		Inactive		Railroad		Rural	
construction activities to determine if any releases are occurring above	e	\boxtimes	Secured	\boxtimes	Residential		Remote	
health based benchmarks. The monitoring will be conducted until the barrier installation is completed.			Unsecured	\boxtimes	Industrial		Other (specify)	
Project Scope of Work and Site Background The potential hazardo	us rolo	osos i	nto the air around an	ongoi	ng fire at the Was	tlaka Land	fill in St.Louis Missouri will bo	
monitored before during and after the barrier installation.	us reie	ases 1		origoi	ing line at the vves	uake Lanu	mii iii St Louis, Missouri wiii be	
Up to 5 monitoring locations surrounding the site in addition to on-site hydrogen sulfide (H2S), carbon monoxide (CO) and volatile organic or conducted. It is planned to co-locate at least one station with MDNR	ompour (most li	nds (V	OCs). Radiation mor					
Health and Safety Approver Comments or Additional Instructions	i:							
Health and Safety Plan Approver Signature:					Da	te:		

Note: A minimum of two persons with appropriate training and medical surveillance must be on site for any fieldwork subject to Level 2 HASP requirements.

Note: A detailed site sketch or figure may be included on Page 10 of 12.



Initial Isolation and Protec	tive Action Distances (for en	nergency response o	pperations only): Use the	2008 Emergency Resp	onse Guidebook (ERG) as appropriate		
	Initial Isolation Distance: This zone should extend in all directions; 660 feet for unknown hazards and 0.5 mile for tanker truck or rail car incidents. NOTE: Keep a maximum distance away for unknown sites until the identity of the materials is determined.						
Subsequent Isolation and Protection Action Zones Based on Air Monitoring Results: NOTE: Distance at sites with unknown hazards should be increased, if necessary, based on air monitoring results.							
Wind Speed and Direction	(Approach from upwind)	Temperature (°F)	Relative Humidity (%)	Probability of Precipitation (%)	Weather Forecast (such as partly cloudy, snow, etc.)		
Speed (mph):	From Direction:		ent weather forecast shall t				
On-Site Supplies:	First Aid Kit	Fire Extinguisher	☐ Air Horn	Oral Therr	nometer Noise Dosimeter		
Known or Anticipated Site	e Hazards or Concerns: (Haz	ards covered by exist	ing Safe Work Practices ar	e listed on the next pag	ge)		
Work on active roadway	у	Overhead utili	ties	Energized elec	ctrical systems		
Onsite laboratory		Buried Utilities	5	Portable hand	tool use		
Explosion or fire hazard	·	Surface or un	derground storage tanks	Portable electr	Portable electrical tool use		
Oxygen deficiency		General slips, trips, falls		Machine guard	Machine guarding		
Unknown or poorly cha	nown or poorly characterized chemical hazards Uneven, muddy, rugged terra		dy, rugged terrain	Portable fire extinguisher use			
	rganic chemicals Lift (man lift, cherry picker) use		herry picker) use	Driving commercial vehicles			
Organic chemicals		Industrial truck (forklift) use		Driving personal vehicles			
Chemical warfare mate	riel	Wood or metal ladder use		Scientific diving operations			
Compressed Gas Cylin	ders	Dangerous go	ods shipped by air	Injury and Illness Prevention Program (California only)			
Asbestos		Elevated work	(over 6' high)	Ergonomics (California only)			
Respirable particulates		Heavy equipm	ent use or operation	☐ Work in strip o	r shaft mines		
Respirable silica		Construction v	vork	Client-specific safety requirements (attach to HASP)			
☐ Blasting and explosives ☐ Excavation or trenching		ATV use					
☐ Non-ionizing radiation (lasers, radiofrequencies, UV) ☐ Benching, shoring, bracing		oring, bracing	Methamphetar	nine lab			
Ionizing radiation (alpha	a, beta, gamma, etc.)	Scaffold use		☐ Working over (or near water		
Heat stress		High noise		☐ Mold			
Cold stress		Grinding oper	ations	Other (insert)			
Explosion or Fire Potentia	al: High	Mediun		Low	Unknown		



Che	mical Products Tetra Tech EM Inc. Will Use or Store On Site: (Attach a Material	Safety Data Sheet [MSDS] for each item.)			
	Alconox or Liquinox Calibration gas (Methane)	Hydrogen gas Isopropyl alcohol			
	Hydrochloric acid (HCl) Calibration gas (Isobutylene)	☐ Household bleach (NaOCI) ☐ HazCat Kit			
	Nitric acid (HNO ₃) Calibration gas (Pentane)	☐ Sulfuric acid (H₂SO₄) ☐ Mark I Kits (number?)			
	Sodium hydroxide (NaOH)	Hexane Other (specify)			
WAF	RNING: Eyewash solution shall be readily available on ALL projects where cor	rosives (acids or bases) are used, including sample preservatives			
	licable Safety Programs and Safe Work Practices (SWP). Attach to HASP:	Tasks Performed At Job Site that are NOT Covered by SWPs			
	DCN 4-03 Demolition and Decontamination	NOTE: Many AHA's can be found on the Health & Safety intranet site at:			
	DCN 4-05 Trenching and Excavation Safety	http://home.ttemi.com/C18/Activity%20Hazard%20Analysis%20Doc um/default.aspx			
	DCN 4-08 Asbestos Protection Program	Attach Activity Hazard Analysis (AHA) for each non-covered task			
	DCN 4-09 Haulage and Earth Moving	outdoor ambient air			
	DCN 4-10 Lead Protection Program	Site walk			
\boxtimes	SWP DCN 5-01 General Safe Work Practices	(non-covered task)			
\boxtimes	SWP DCN 5-02 General Safe Work Practices HAZWOPER	(non-covered task)			
	SWP DCN 5-03 Safe Work Practices for Office Employees	(non-covered task)			
	SWP DCN 5-04 Safe Drilling Practices				
	SWP DCN 5-05 Safe Direct Push (GeoProbe) Practices	Tetra Tech Employee Training and Medical Requirements:			
	SWP DCN 5-06 Working Over or Near Water				
	SWP DCN 5-07 Use of Heavy Equipment	Basic Training and Medical			
	SWP DCN 5-08 Special Site Hazards (Firearms, Remote Sites, Mines, aircraft, etc.)	☐ Initial 40 Hour Training			
Ц	SWP DCN 5-09 Safe Electrical Work Practices	8-Hour Supervisor Training (one-time)			
Ц	SWP DCN 5-10 Fall Protection Practices	Current 8-Hour Refresher Training Current Medical Clearance (including respirator use)			
Ц	SWP DCN 5-11 Portable Ladder Safety	Current Medical Clearance (including respirator use)			
Ц	SWP DCN 5-12 Drum and Container Handling Practices	Current First Aid Training			
Ц	SWP DCN 5-13 Flammable Hazards and Ignition Sources	Current CPR Training			
Ц	SWP DCN 5-14 Spill and Discharge Control Practices	Current Respirator Fit-Test			
Ц	SWP DCN 5-15 Heat Stress	Other Specific Training and Madical Suggestions Beguirements			
	SWP DCN 5-16 Cold Stress	Other Specific Training and Medical Surveillance Requirements Confined Space Training			
	SWP DCN 5-17 Biohazards	Level A Training			
Ц	SWP DCN 5-18 Underground Storage Tank Removal Practices	Radiation Training			
Ц	SWP DCN 5-19 Safe Lifting Procedures	OSHA 10-hour Construction Safety Training			
	SWP DCN 5-22 Hydrographic Data Collection	OSHA 30-hour Construction Safety Training OSHA 30-hour Construction Safety Training			
\vdash	SWP DCN 5-23 Permit-Required Confined Space Entry Practices	Asbestos Awareness Training			
Ц	SWP DCN 5-24 Non-Permit-Required Confined Space Entry Practices	Asbestos Awareness Training Asbestos B-Reader X-Ray			
	SWP DCN 5-26 Prevention of Sun Exposure	☐ Blood Lead Level and ZPP Pre, during and Post-Project			
	SWP DCN 5-27 Respirator Cleaning Practices	Urinary Arsenic Level Pre and Post-Project			
Ц	SWP DCN 5-28 Safe Use Practices for Use of Respirators				
	SWP DCN 5-29 Respirator Qualitative Fit Testing Procedures	☐ Other Other			
	SWP DCN 5-30 Laboratory Soil Testing Safe Work Practices	U Otilei			



Materials Present or Suspected at Site	Highest Observed Concentration (specify units and sample medium)	Exposure Limit (specify ppm or mg/m³)	IDLH Level (specify ppm or mg/m³)	Primary Hazards of the Material (explosive, flammable, corrosive, toxic, volatile, radioactive, biohazard, oxidizer, or other)	Symptoms and Effects of Acute Exposure	Photoionization Potential (eV)
sulfur dioxide (SO2)	U	PEL = 15 mg/m3 REL = .10 mg/m3 TLV =	100 mg/m3	toxic	Irritation eyes, nose throat,\; rhin; chocking, cough; reflex bronchionstriction	12.3
hydrogen sulfide (H2S),	U	PEL = 20 ppm REL = 15 mg/m3 TLV =	100 ppm	Toxic, flammable	Irrit eyes,resp sys; apnea, coma, convuls; corn visic; dizz, head,f tg, irrit, insom, derm	NA
carbon monoxide (CO)	U	PEL = 55 mg/m3 REL = 40 mg/m3 TLV = NA	1200 ppm	Flammable, toxic	head, tachypnea, nau, weak, blurred vision, dizziness, slurred speech, confusion, convulsions	14.01
radon, alpha, beta and gamma	U	PEL =. REL = TLV =		radioactive		NA
Non-specified volatile organic compounds	U	PEL = Various REL = TLV =	Various	Volatile, flammable	Various, but include nausea, headache, and vomiting.	Various
		PEL = REL = TLV =				
		TLV =				

Specify Information Sources: For example: NIOSH Pocket Quide to Hazardous Chemicals, September 2005 and American Conference of Governmental Industrial Hygienists (ACGIH). "Threshold Limit Values and Biological Exposure Indices for 2009."

Note: In the Exposure Limit column, include Ceiling (C) and Short-Term Exposure Limits (STEL) if they are available. Also, use the following short forms and abbreviations to complete the table above.

A = Air

CARC = Carcinogenic eV = Electron volt U = Unknown

IDLH = Immediately dangerous to life or health

mg/m³ = Milligram per cubic meter

NA = Not available NE = None established PEL = Permissible exposure limit

ppm = Part per million

REL = Recommended exposure limit

S = Soil

TLV = Threshold limit value



Note: If no contingency level of protection is selected, all employees covered under this plan must evacuate the immediate site area if air contaminant le require upgrading PPE. Level A field work requires a Level 3 HASP. This information is available on the chemical hazards page of this HASP.					
Field Activities Covered Under this HASP:					
		Level of F	Protection ¹	Date of	
Task Description		Primary	Contingency	Activities	
1 Ambient air monitoring		□ A □ B □ C ☑ D	□ A □ B ⊠ C □ D	May 31 forward	
2		A B C D	□ A □ B □ C □ D		
3		ABBCDD	A B C D		
4		A B C D	A B C D		
5		A B C D	A B C D		
Site Personne	l and Responsibilities (inclu	de subcontractors):			
Employee Name and Office Code / Location	Task(s)		Responsibilities		
David Kinroth	1 ·	(SSC) aware of pertine communications with c longer than one conseconducting one field au	•	, and maintains ir projects lasting onsible for	
,	1	(SSC) aware of pertine	rects feld activities, makes site sa nt project developments and plans ne Project Manager and the client a	, and maintains	
·		equipment (PPE) is av personnel and subcont or may be exposed to a the HASP; identifies ar site hazards to all pers	r (SSC): Ensures that appropriate allable, enforces proper use of PPE ractors; suspends investigative wo an immediate health hazard; implered controls site hazards when possionnel; and reports any deviations of described in the health and safety page.	by on-site k if personnel are nents and enforces ble; communicates bserved from	
•		Alternate Site Safety C	oordinator (if any)		
		team leader, and SSC,	letes tasks as directed by the proje and follows the HASP and all SWf a Tech, Inc., Health and Safety Mar	s and guidelines	
		be identified by name): work in accordance wit safety meetings and fol	ontractor personnel on site(a subco Completes tasks as outlined in the h the contract. Participates in all T llows all procedures and guidelines ompany health and safety plan and	e project scope of etra Tech on-site s established in this	

Note:

1. See next page for details on levels of protection



NOTE: Contingency level of protection section should be completed only if the upgraded level of protection is immediately available at the job site. If no contingency level of protection is denoted, all employees covered under this HASP must evacuate the immediate site area if air contaminant levels would require an upgrade of PPE.

Protective Equipment: (Indicate type or material as necessary for each task.)

Tas k	Primary Level of Protection (A,B,C,D)	PPE Component Description (Primary)	Contingency Level of Protection (A, B, C, D)	PPE Component Description (Contingency)
1	D	Respirator type: NA Cartridge type (if applicable): NA CPC material: NA Glove material(s): Jersey & nitrile Boot material: Steel toe and shank Other: Safety glasses, hard hat, safety vest	С	Respirator type: Full-face APR Cartridge type (if applicable): Organic vapors, P100 CPC material: Tyvek coveralls Glove material(s): Nitrile Boot material: Steel toe and shank Other: hard hat, safety vest
2		Respirator type: Cartridge type (if applicable): CPC material: Glove material(s): Boot material: Other:		Respirator type: Cartridge type (if applicable): CPC material: Glove material(s): Boot material: Other:
3		Respirator type: NA Cartridge type (if applicable): CPC material: NA Glove material(s): Boot material: Other:		Respirator type: Cartridge type (if applicable): CPC material: Glove material(s): Boot material: Other:
4		Respirator type: Cartridge type (if applicable): CPC material: Glove material(s): Boot material: Other:		Respirator type: Cartridge type (if applicable): CPC material: Glove material(s): Boot material: Other:
5		Respirator type: Cartridge type (if applicable): CPC material: Glove material(s): Boot material: Other:		Respirator type: Cartridge type (if applicable): CPC material: Glove material(s): Boot material: Other:

Respirator Notes:

Respirator cartridges may only be used for a maximum time of 8 hours or one work shift, whichever is less, and must be discarded at that time. For job sites with organic vapors, respirator cartridges may be used as described in this note as long as the concentration is less than 200 parts per million (ppm), the being point is greater than 70 Celsius, and the relative humidity is less than 85 percent. If any of these levels are exceeded, a site-specific respirator cartridge change-out schedule must be developed and included in the HASP using Tetra Tech Form RP-2 (Respiratory Hazard Assessment Form)

Notes:

All levels of protection must include eye, head, and foot protection.

CPC = Chemical protective clothing

Thermoluminescent Dosimeter (TLD) Badges must be worn during all field activities on sites with radiation hazards. TLDs must be worn under CPC.

11 February 2010 Page 6 of 12

Monitoring Equipment: All monitoring equipment on site must be calibrated before and after each use and results recorded in the site logbook						
Instrument (Check all required)	Task	Instrument Reading	Action Guideline	Comments		
Combustible gas indicator model:	☐ 1 ☐ 2	0 to 10% LEL	Monitor; evacuate if confined space	-		
	3	10 to 25% LEL	Potential explosion hazard; notify SSC			
	4 5	>25% LEL	Explosion hazard; interrupt task; evacuate site; notify SSC			
Oxygen meter model:	□ 2	>23.5% Oxygen	Potential fire hazard; evacuate site			
	3	23.5 to 19.5% Oxygen	Oxygen level normal			
	☐ 4 ☐ 5	<19.5% Oxygen	Oxygen deficiency; interrupt task; evacuate site; notify SSC	·		
Radiation survey meter model:	1 2	Normal background	Proceed	Annual exposure not to exceed 1,250 mrem per quarter		
TLDs, Alpha Track Detectors, Particulate monitors (Radecos), E-Perms (Radon), and Saphymo Genitron Gamma Tracers,	□ 3	Two to three times background	Notify SSC	Background reading must be taken in an area known to be free of radiation sources.		
and supriying contact cannot record,	☐ 4 ☐ 5	>Three times background	Radiological hazard; interrupt task; evacuate site; notify RSO			
Photoionization detector model:		Any response above background to 5 ppm above background	Level B is recommended Level C ^a may be acceptable	These action levels are for unknown gases or vapors. After the contaminants are identified, action levels should be based on the specific contaminants involved.		
☐ 11.7 eV ☐ 10.6 eV ☐ 9.8 eV	2 3	> 5 to 500 ppm above background	Level B	specific contaminants involved.		
Other (specify):	☐ 4 ☐ 5	> 500 ppm above background	Level A	·		
Flame ionization detector model:	1 2	Any response above background to 5 ppm above background	Level B is recommended Level C ^a may be acceptable	These action levels are for unknown gases or vapors. After the contaminants are identified, action levels should be based on the		
	3	>5 to 500 ppm above background	Level B	specific contaminants involved.		
	4 5	>500 above background	Level A			
Detector tube models:	1 2	Specify: < 1/2 the PEL > 1/2 the PEL	Specify:	The action level for upgrading the level of protection is one-half of the contaminant's PEL. If the PEL is reached, evacuate the site and notify a safety specialist		
	3 4 5					
Other (specify): MultiRae / AreaRae / PbRae	 □ 1 □ 2 □ 3 □ 4 □ 5 	Specify: CO – 9ppm SO2 – Day:0.10 ppm Night: 0.40 ppm H2S – Day: 0.30 ppm Night:1.00 ppm VOC – Day: 5.0 ppm Night: 10.0 ppm LEL – Day: 5% Night: 10% Gamma – 100 uR/Hour	Specify: Alarm levels: additional monitoring will be conducted to determine if additional actions are required.			

LEL=Lower explosive limit

mrem=Millirem

PEL=Permissible exposure limit

eV= electron volt LEL=Lower explosive limit mrem=Millirem PEL=Permissible exposure limit ppm=Part per million

a. Level B is required when chemical hazards are present, but are uncharacterized. Level C may be acceptable for certain tasks in some situations. Ifyou are uncertain, consult your RSO.



Project-Specific Industrial Hygiene Requirements	Emergency Contacts:	Telephone No.
OSHA-Regulated Chemicals*:	WorkCare and Incident Intervention 888.44	9.7787, or 800.455.6155
Check any present on the job site in any medium (air, water, soil)	Tetra Tech EMI 24-hour Anonymous Hazard Reporting Line	866.383.8070
No chemicals below are located on the job site	U.S. Coast Guard National Response Center	800.424.8802
Friable Asbestos	InfoTrac	800.535.5053
Silica, crystalline	Poison Control	800.222.1222
alpha-Napthylamine	Fire department	911 (417) 623-0403
Methyl chloromethyl ether	Police department	911 (417) 623-3131
3,3'-Dichlorobenzidine (and its salts)	Personnel Call-Down List:	011 (117) 020 0101
bis-Chloromethyl ether		
beta-Napthylamine •	Job Title or Position: Name	Cell Phone:
Benzidine	Regional Safety Officer Denny Cox Project Manager: David Kinroth	(816) 668-7464 (314) 517-6798
4-Aminodiphenyl	Field Team Leader:	(314) 317-07-50
Ethyleneimine	Site Safety Coordinator (SSC):	
beta-Propiolactone	Subcontractor SSC:	
2-Acetylaminoflourene		
4-Dimethylaminoazobenzene	Medical and Site Emergencies:	
N-nitrosomethylamine	Signal a site or medical emergency with three blasts of a loud horr	(car horn, fog horn, or
☐ Vinyl chloride	similar device). Site personnel should evacuate to the area ofsafe	
Inorganic arsenic	the site map.	
Lead	Hospital Name: SSM DePaul Health Center	
Chromium (VI)	Address: 12202 DeBeul Prive Bridgeton MO 62044	
Cadmium	Address: 12303 DePaul Drive, Bridgeton, MO 63044	
Benzene		
Coke oven emissions	General Phone: Emergency Phone:	(314) 344-6000 911
1,2-Dibromo-3-chloropropane	Ambulance Phone:	911
Acrylonitrile		, _
Ethylene oxide	Hospital called to verify emergency services are offered? YES	NO 🗌
Formaldehyde Methylenedianiline	Step-by-step Route to Hospital: (see Page11 of 12 for route map)	
1,3-Butadiene Methylene chloride	1. 1. Head southwest on Taussig Rd toward St Charles Rock Rd	0.2 mi
	2. Turn left onto St Charles Rock Rd	1.3 mi
* NOTE: Many states, including California and New Jersey, have chemical-specific worker protection requirements and standards for many chemicals and	3. Turn right onto De Paul Dr	289 ft
known or suspected carcinogens.	4. Turn right to stay on De Paul Dr	0.1 mi
	5. Turn left to stay on De Paul Dr	0.2 mi
	6. Turn right to stay on De Paul Dr Destination will be on the right	423 ft

Note: This page must be posted on site.

Decontaminati	on Procedures	Emergency Response Planning
The site safety coordinator overseas implementation of project decontamination procedures and is responsible for ensuring they are effective.		During the pre-work briefing and daily tailgate safety meetings, all on-site employees will be trained in the provisions of emergency response planning, site communication systems, and site evacuation routes.
Personnel Decontamination	Decontamination Equipment	In the event of an emergency that necessitates evacuation of a work task
Level D Decon - 🗌 Wet 🔀 Dry	Washtubs	 area or the site, the following procedures will take place. The Tetra Tech SSC will contact all nearby personnel using the on-site
Level C Decon - 🗌 Wet 🛛 Dry	⊠ Buckets	communications to advise the personnel of the emergency. • The personnel will proceed along site roads to a safe distance upwind from
Level B Decon – Briefly outline the level B decontamination methods to be used on	Scrub brushes	the hazard source. The personnel will remain in that area until the SSC or an authorized
a separate page attached to this HASP.	Pressurized sprayer	individual provides further instructions.
Level A Decon – A Level 3 HASP is required. Notify your regional health and	Detergent [Alconox]	In the event of a severe spill or a leak, site personnel will follow the
safety representative and health and	Solvent [Type]	 procedures listed below. Evacuate the affected area and relocate personnel to an upwind location.
safety director. Equipment Decontamination	☐ Household bleach solution	Inform the Tetra Tech SSC, a Tetra Tech office, and a site representative
	Concentration/Dilution:	 immediately. Locate the source of the spill or leak, and stop the flow if it is safe to do so.
All tools, equipment, and machinery from the Exclusion Zone (hot) or	Deionized water	Begin containment and recovery of spilled or leaked materials.
Contamination Reduction Zone (warm) are decontaminated in the CRZ before	Disposable sanitizer wipes	Notify appropriate local, state, and federal agencies.
they are removed to the Support Zone (cold). Equipment decontamination	Facemask sanitizer powder	In the event of severe weather, site personnel will follow the procedures listed below.
procedures are designed to minimize the potential for hazardous skin or inhalation	☐ Wire brush	 Site work shall not be conducted during severe weather, including high winds and lightning.
exposure, cross-contamination, and chemical incompatibilities.	Spray bottle	In the event of severe weather, stop work, lower any equipment (drill rigs) and evacuate the affected area.
Respirator Decontamination	Tubs / pools	Severe weather may cause heat or cold stress. Refer to SWPs 5-15 and 5-16 for information on both.
Respirators are decontaminated in	Banner/barrier tape	
compliance with SWP 5-27 and should be included with this HASP.	Plastic sheeting	All work-related incidents must be reported. According to TtEMI's reporting procedures, for non-emergency incidents you should:
Waste Handling for Decontamination	Tarps and poles	Notify WorkCare and Incident Intervention at 888.449.7787, or 800.455.6155
Procedures for decontamination waste	⊠ Trash bags	Notify your Project Manager or Regional Safety Officer (RSO) via phone
disposal meet all applicable local, state, and federal regulations.	Trash cans	 immediately. Complete a "Tetra Tech Incident Report" (Form IR) within 24 hours and send
	Duct tape	it to your RSO. If an injury or illness has occurred, the Form IR-A and the WorkCare HIPAA form must be completed at the same time the Form IR is
	□ Paper towels	completed.
	Folding chairs	
	Other	




 Site Map (May be drawn after crews arrive onsite	or inserted using aerial photographs, site figures, etc.):	
		·
		·
•		
	1	
		·
	•	



Hospital Route Map (attach or insert):

Taussig Rd to 12303 De Paul Dr, Bridgeton, MO 63044 - Googl... https://maps.google.com/maps?saddr=earth city missouri&dadd...



Note: A dry-run should be conducted to establish a physical location associated with the map included in the HASP. Verbal verification from the hospital emergency room should also be obtained to ensure that the hospital will accept chemically contaminated patients.



APPROVAL AND SIGN-OFF FORM

Project No.: x9025.14.0058.000

I have read, understood, and agree with the information set forth in this Health and Safety Plan and will follow the direction of the Site Safety Coordinator (SSC) as well as procedures and guidelines established in the Tetra Tech, Inc., Health and Safety Manual. I understand the training and medical requirements for conducting field work and have met these requirements.

Tetra Tech has prepared this plan solely for the purpose of the health and safety protection of Tetra Tech employees. Subcontractors, visitors, and others at the site, while required to read and follow the provisions outlined in this plan at a minimum, should refer to their safety program for specific information related to their health and safety protection.

Name	Company / Agency / Organization	Signature	Date
		·	
		•	
ttood and amon with the	information and footh in this Haulth and Cafety Dlaw	and a series with a selection with a selection while LIACO	
d, understood, and agree with the d in the Tetra Tech, Inc., Health	e information set forth in this Health and Safety Plan and Safety Manual.	and comply with and will enforce this HASP, as	well as procedures and gu
Name	Project-Specific Position	Signature	Date
David Kinroth	Project Manager		
	Field Team Leader		
	Site Safety Coordinator		
	Subcontractor SSC		

Note: Use Additional sheets as necessary to ensure that all personnel sign and affirm this document.



VOLUNTARY PROTECTION PROGRAM



Management Leadership

Lead by example. Good managers recognize the benefits of a strong safety program and ensure that their personnel and subcontractors have the right tools, equipment, and attitude to work safely.

Some areas where effective management leadership for safety can be demonstrated include:

- Provide visible safety leadership start meetings with a safety topic, integrate safety into planning, scheduling, and budgeting processes, take personal action to resolve safety issues.
- Become involved in incident reporting, investigation, corrective action share lessons learned.
- · Include subcontractors in your safety program and oversee their work.

Employee Involvement

Get involved! Take personal action and work directly with your supervisor daily to identify, control, or eliminate potential safety hazards.

Other ways to become involved in the safety program and improve work conditions include:

- Initiate hazard reports to identify hazards, suggest improvements, and recognize safe behaviors
- Participate in safety meetings and worksite safety inspections (daily, weekly, monthly, and quarterly)
- · Participate in incident reports, investigations, corrective actions, and Lessons Learned

Worksite Analysis

The process of identifying and evaluating potential hazards is a critical element in achieving zero incidents and creating low risk and hazard-free work areas.

Worksite analysis methods used to identify and evaluate potential hazards include:

- · Safety inspections (daily, weekly, monthly, and quarterly)
- · Develop or review safe work procedures, AHA's, and the HASP
- · Monitoring for air quality, heat stress, noise, ergonomics and other job hazards

Hazard Prevention and Control

Eliminating hazards from your job, preventing new hazards, and controlling known hazards are fundamental parts of the projects safety program.

Important points include:

- · Control hazards by:
 - Installing and maintaining Engineering Controls
 - Following Administrative/Work Practice Controls (HASP, AHAs, and safe work practices)
 - Specifying and wearing Personal Protective Equipment where needed
- · Perform integrated safety reviews for new or modified work tasks
- Consult with qualified medical and safety professionals as needed

Safety and Health Training

Effective safety training is an important element in incident prevention. Remember, if you are unfamiliar with the work or feel that you don't have the necessary training, speak up and notify your team leader or project manager.

Safety training methods that may be used at the project include:

- New employee orientation, including HASP and task-specific training
- Project meetings, daily briefings, and/or task briefings
- · Lessons learned and monthly safety communications

Emergency Contacts

- WorkCare For issues requiring an Occupational Health Physician; assistance is available 24 hours per day, 7 days per week.
- InfoTrac For issues related to incidents involving the transportation of hazardous chemicals; this hotline provides accident assistance 24 hours per day, 7 days per week
- U.S. Coast Guard National Response Center For issues related to spill containment, cleanup, and damage assessment; this hotline will direct spill information to the appropriate state or region

Poison Control Center - For known or suspected poisoning.

Limitations:

The Level-Two HASP is not appropriate in some cases:

- Projects involving unexploded ordnance (UXO), radiation sources as the primary hazard, or known chemical/biological weapons site must employ the Level 3 HASP
- Projects of duration longer than 90 days may need a Level 3 HASP (consult your RSO)

Decontamination:

- Decontamination Solutions for Chemical and Biological Warfare Agents^a: PPE and equipment can be decontaminated using 0.5 percent bleach (1 gallon laundry bleach to 9 gallons water) for biological agents (15 minutes of contact time for anthrax spores; 3 minutes for others) followed by water rinse for chemical and biological agents. In the absence of bleach, dry powders such as soap detergents, earth, and flour can be used. The powders should be applied and then wiped off using wet tissue paper. Finally, water and water/soap solutions can be used to physically remove or dilute chemical and biological agents. Do not use bleach solution on bare skin; use soap and water instead. Protect decontamination workers from exposure to bleach.
- **Decontamination for Radiological and Other Chemicals:** Primary decontamination should use Alconox and water unless otherwise specified in chemical specific information resources. The effectiveness of radiation decontamination should be checked using a radiation survey instrument. Decontamination procedures should be repeated until the radiation meter reads less than 100 counts per minute over a 100-square-centimeter area when the probe is held 1 centimeter from the surface and moving slower than 2.5 centimeters per second.
- **Decontamination Corridor:** The decontamination setup can be adjusted to meet the needs of the situation. The decontamination procedures can be altered to meet the needs of the specific situation when compound- and site-specific information is available.
- **Decontamination Waste:** All disposable equipment, clothing, and decontamination solutions will be double-bagged or containerized in an acceptable manner and disposed of with investigation-derived waste.
- **Decontamination Personnel:** Decontamination personnel should dress in the same level of PPE or one level below the entry team PPE level.
- All investigation-derived waste should be left on site with the permission of the property owner and the EPA on-scene coordinator. In some instances, another contractor will dispose of decontamination waste and investigation-derived waste. DO NOT place waste in regular trash. DO NOT dispose of waste until proper procedures are established.

Notes:

^a Source: Jane's Information Group. 2002. Jane's Chem-Bio Handbook. Page 39.



TETRA TECH, INC. DAILY TAILGATE SAFETY MEETING FORM

Date: Time:	Project No.:
Client:	Site Location:
Site Activities Planned for Today:	i
Weather Conditions:	
Safety To	pics Discussed
Protective clothing and equipment:	
· · · ·	
Chemical and physical hazards:	
·	
Emergency procedures:	
Equipment hazards:	
Other:	
Att	tendees
Printed Name	Signature
Meeting Conducted by:	
Name	Signature



TETRA TECH EM INC. HEALTH AND SAFETY PLAN AMENDMENT

afe Work Practices or Act	ivity Hazard Analyses:	·
AMENDME	NT APPROVAL	
Name	Signature	Date
	AMENDME	AMENDMENT APPROVAL



TETRA TECH, INC. FIELD AUDIT CHECKLIST

Project Name:	Project No.:	
Field Location:	Completed by: _	
Project Manager:	Site Safety Coordinator:	

Projec	t Manager: Site Safety Coordinator:				
General Items			In Compliance?		
Health	and Safety Plan Requirements	Yes	No	NA	
1	Approved health and safety plan (HASP) on site or available				
2	Names of on-site personnel recorded in field logbook or daily log				
3	HASP compliance agreement form signed by all on-site personnel				
4	Material Safety Data Sheets on site or available				
5	Designated site safety coordinator physically present on jobsite				
6	Daily tailgate safety meetings conducted and documented on Form HST-2				
7	Documentation available proving compliance with HASP requirements for medical examinations, fit testing, and training (including subcontractors)	!			
8	HASP onsite matches scope of work being conducted				
9	Emergency evacuation plan in place and hospital located				
10	Exclusion, decontamination, and support zones delineated and enforced				
11	HASP attachments present onsite (VPP sheet, audit checklist, AHA, etc.)				
12	Illness and injury prevention program reports completed (California only)				
Emerg	ency Planning				
13	Emergency telephone numbers posted				
14	Emergency route to hospital posted				
15	Local emergency providers notified of site activities				
16	Adequate safety equipment inventory available				
17	First aid provider and supplies available				
18	Eyewash solution available when corrosive chemicals are present				
Air Mo	nitoring				
19	Monitoring equipment specified in HASP available and in working order				
20	Monitoring equipment calibrated and calibration records available				
21	Personnel know how to operate monitoring equipment and equipment manuals available on site				
22	Environmental and personnel monitoring performed as specified in HASP				

	Safety Items	In C	omplia	nce?	
Personal Protection			No	NA	
23	Splash suit, if required				
24	Chemical protective clothing, if required				
25	Safety glasses or goggles (always required)				
26	6 Gloves, if required				
27	27 Overboots, if required				
28	28 Hard hat (always required)				
29	9 High visibility vest, if required				
30	Hearing protection, if required				
31	Full-face respirator, if required				
Instrumentation					
32	Combustible gas meter and calibration notes				
33	Oxygen meter and calibration notes				
34	Organic vapor analyzer and calibration notes				
Supp	lies				
35	Decontamination equipment and supplies				
35	Fire extinguishers				
37	Spill cleanup supplies				
Corrective Action Taken During Audit:					
Note:	: NA = Not applicable				
Auditor's Signature Site Safety Coordinator's Signature		or's Signature	!		
Date					

				ACTIVITY HAZARD ANALYSIS (AHA
Tetra Tech, In	C.			Tetra Tech EM Inc
1000 1000 1	1302			(Insert Task Name Here
				Task Description
The AHA contains potential had equipment), inspections, and Insert a brief narrative described by step through the step by step by step by step by step through the step by ste	azards p training. <i>ription o</i> <i>ugh the</i>	osed by each major step The hazard controls liste of each task to be comp whole process. For ea	in this to ded below bleted.	
	Hazard			Actions
Task Steps		Potential Hazards		Critical Safety Procedures and Controls
Insert additional rows as ne	eded			
Equipment to be Used		Inspection Requirem	<u>nents</u>	Training Requirements
Assessed By	Nar	me	Signati	ature Date
Approved By	Nar	me	Signati	ature Date